

16300031/01



| | |
|-----------------------|---------------------------|
| <p>(A)</p> <p>X 1</p> | <p>(B)</p> <p>X 1</p> |
| | <p>(C)</p> <p>4MM X 2</p> |
| | <p>(D)</p> <p>3MM X 1</p> |

The assembly sequence consists of four main diagrams:

- Diagram 1:** Shows the initial assembly of part A, a stepped metal frame with four shelves.
- Diagram 2:** Shows part B (a small box) being placed on top of the highest shelf of part A. The combined assembly is labeled "A+B".
- Diagram 3:** Shows part C (two screws) being inserted into the top of the box from part B. A circular inset provides a magnified view of the screws being inserted into the top edge of the box.
- Diagram 4:** Shows part D (a curved pin) being inserted into the top of the box from the side. The final assembly is labeled "A+B+C+D".