







TINO OFFICE Standelement 3L







00030132/05
1460953













40
MIN



Ø8
Ø5







A0 8 x 30mm 	B1 7x 50 mm 	C0  x12
C2  x20	C7 16mm  x20	C17  x2
D0 3 x 15 mm  x28	D8 4.2 x 13 mm  x1	D21 5 x 13 mm  x1
D31 6.3 x 13 mm  x24	E0 5 x 50 mm 8 x 50 mm  x1	K 4mm  x1
L3  x3	M1  x22	N14 L-350  x3
P0  x1	T11  x4	LOGO... x1



1	492	384	16	x1	1/1
2	492	384	16	x1	1/1
3	864	385	16	x1	1/1
4	864	385	16	x1	1/1
5	452	259	16	x1	1/1
6	350	260	16	x1	1/1
7	350	260	16	x1	1/1
8	452	159	16	x2	1/1
9	350	160	16	x2	1/1
10	350	160	16	x2	1/1


11	521	425	16	x1	1/1
12	521	214	16	x2	1/1
13	462	344	3	x3	1/1
14	841	502	3	x1	1/1
					1/1







1

A0	8 x 30mm	x4	C7	16mm	x4






2

(A0)	8 x 30mm	x4	(C7)	16mm	x4	(D8)	4.2 x 13 mm	x1
								
(D21)	5 x 13 mm	x1	(P0)		x1			
								






3

(C2)	x4	(D31)	6.3 x 13 mm	x12	(N14)	L-350	x3
-------------	-----------	--------------	-------------	------------	--------------	-------	-----------





4



(C2)	x4	(D31)	6.3 x 13 mm	x12	(N14)	L-350	x3
-------------	-----------	--------------	-------------	------------	--------------	-------	-----------





5



6





7






8

(C2)  x12	(D0)  3 x 15 mm x6	(L3)  x3
--	---	---





9

(B1)  7x 50 mm x12	(K)  4mm x1
---	--




10









11



(D0)	3 x 15 mm	x12	(M1)		x12




a=b




12





13





14



15







16






17

(D0)	3 x 15 mm	x10	(M1)		x10
					



18

(C17)		x2
		







19

E0





5 x 50 mm

x1

8 x 50 mm



20



21

