


# TINO OFFICE Standelement 1T128














00030132/02  
1460950






## Variant A




## Variant B




**30**  
MIN




<b>A0</b> 8 x 30mm 	<b>x8</b>	<b>B5</b> Ø5mm 	<b>x10</b>	<b>C0</b> 	<b>x4</b>
<b>C2</b> 	<b>x8</b>	<b>C7</b> 16mm 	<b>x8</b>	<b>C17</b> 	<b>x2</b>
<b>D0</b> 3 x 15 mm 	<b>x14</b>	<b>D8</b> 4.2 x 13 mm 	<b>x1</b>	<b>D10</b> 4 x 16 mm 	<b>x6</b>
<b>D21</b> 5 x 13 mm 	<b>x1</b>	<b>E0</b> 5 x 50 mm 8 x 50 mm 	<b>x1</b>	<b>J0</b> 	<b>x3</b>
<b>J3</b> 	<b>x3</b>	<b>J10</b> 	<b>x3</b>	<b>L3</b> 	<b>x1</b>
<b>M1</b> 	<b>x12</b>	<b>P0</b> 	<b>x1</b>	<b>Q3</b> 	<b>x8</b>
<b>T11</b> 	<b>x4</b>	<b>LOGO...</b>		<b>x1</b>	




<b>1</b>	492	384	16	x1	1/2
<b>2</b>	1236	385	16	x1	1/2
<b>3</b>	1236	385	16	x1	1/2
<b>4</b>	492	360	16	x2	1/2
<b>5</b>	526	403	32	x1	2/2
<b>6</b>	1231	521	16	x1	2/2
<b>7</b>	1229	502	3	x1	2/2
					1/2







**1**

<b>A0</b>	8 x 30mm	<b>x4</b>	<b>C7</b>	16mm	<b>x4</b>




**2**

<b>C2</b>	<b>x4</b>	<b>D8</b>	4.2 x 13 mm	<b>x1</b>	<b>D21</b>	5 x 13 mm	<b>x1</b>
<b>P0</b>	<b>x1</b>						




3

<b>A0</b>	8 x 30mm	<b>x2</b>	<b>C7</b>	16mm	<b>x2</b>	<b>C2</b>	<b>x2</b>
-----------	----------	-----------	-----------	------	-----------	-----------	-----------





4


<b>A0</b>	8 x 30mm	<b>x2</b>	<b>C7</b>	16mm	<b>x2</b>	<b>C2</b>	<b>x2</b>
-----------	----------	-----------	-----------	------	-----------	-----------	-----------





5




6



7




8







T11

x4






9

<b>(D0)</b> 3 x 15 mm 	<b>x12</b>	<b>(M1)</b> 	<b>x12</b>
---	------------	--	------------



10

<b>(C17)</b> 	<b>x2</b>
---	-----------



# 11

**E0** **x1**

5 x 50 mm  
8 x 50 mm







Diagram showing a 5x50mm screw and an 8x50mm cam bolt.



# 12

**Q3** **x8**







Diagram showing a T-shaped bracket labeled 'Q3'.




# Variant A




## 13

<b>D0</b>	3 x 15 mm	<b>x2</b>	<b>D10</b>	4 x 16 mm	<b>x6</b>	<b>J0</b>		<b>x3</b>
								
<b>J10</b>		<b>x3</b>	<b>L3</b>		<b>x1</b>			
								



## 14


<b>J3</b>		<b>x3</b>
		




# Variant B




## 13

<b>D0</b>	3 x 15 mm	<b>x2</b>	<b>D10</b>	4 x 16 mm	<b>x6</b>	<b>J0</b>		<b>x3</b>
								
<b>J10</b>		<b>x3</b>	<b>L3</b>		<b>x1</b>			
								



## 14

<b>J3</b>		<b>x3</b>
		



# 15

<b>B5</b> Ø5mm 	<b>x10</b>	<b>C0</b> 	<b>x4</b>	<b>LOGO...</b>	<b>x1</b>
---	------------	---	-----------	----------------	-----------

