







Assembly Instruction

KOMMODE MALIN

Article number: 05540001/05



286 X 1 PCS	249 X 7 PCS	5694 X 6 PCS	565 X 1 PCS	180964 X 1 PCS	122439 X 4 PCS	145662 X 16 PCS
95200 X 1 PCS	147 X 38 PCS	146 X 12 PCS	175 X 16 PCS	361 X 8 PCS	172 X 12 PCS	4997 X 16 PCS
81062 X 4 PCS	103 X 4 PCS	100 X 28 PCS	101 X 28 PCS	298176 X 8 PCS	150217 X 4 SET	150218 X 4 SET
298172 X 2 PCS	298171 X 1 PCS	298173 X 3 PCS	157124 X 28 PCS	22018 X 24 PCS	298177 X 5 PCS	298188 X 6 PCS

1


The diagram illustrates the first step of assembly for a rectangular frame (2). It shows the installation of four legs (249) and four casters (100) onto the frame. The frame is shown in two orientations to demonstrate the correct placement of the parts. The following parts are identified:

- 249**: Legs (shown in two orientations).
- 298188**: Screws used to secure the legs.
- 100**: Casters (shown in two orientations).
- 172**: Screws used to secure the casters.
- 101**: Screws used to secure the casters.


TURN AROUND THE PIECE (PART) !

[illegible]


3




4




7




8




9




10




11




12




13



14



15



16

