




Assemble instruction







27980110/03





1350348

NOVA










A	x18	B	x34	C	x12	D	x8	E	x64	F	x4	G	x1
													
6x35mm		Ø15x12mm		8x30mm		6x30mm		3.5x14mm		7x50mm		M4	
H	x2	I	x12	J	x4	K	x8	L	x2	M	x2	N	x2
													
M6x12mm		M6x28mm		M6x50mm		M6x18mm		6x30mm		Ø30x15mm		4x60mm	
O	x16	P	x4	Q	x1	R	x16	S	x8	T	x8	U	x2
													
5x20mm												7x40mm	
V	x12												
													
Ø20mm													




Assembly details




1





A	x4
	
6x35mm	

B	x4
	
Ø15x12mm	


S	x4
	


2




A	x2
	
6x35mm	

3




B	x4	S	x4
			
Ø15x12mm			


4



x 2


A	x12	C	x4
			
6x35mm		8x30mm	

5




B	x8
	
Ø15x12mm	

6




B	x4	D	x4
			
Ø15x12mm		6x30mm	




C	x6
8x30mm	

8




U	x2	G	x1
7x40mm		M4	

9




B	x2
	
Ø15x12mm	


10



11




12



G	x1	J	x4	P	x4
M4		M6x50mm			

13




G	x1
	
M4	

H	x2
	
M6x12mm	

I	x12
	
M6x28mm	

Q	x1
	


14




C	x2
	
8x30mm	

D	x4
	
6x30mm	


15




16



17




18







O	x16
	
5x20mm	

19




20

x 2




K	x4	G	x1
			
M6x18mm		M4	



21




22



23



E	x32
	
3.5x14mm	

24

